

CUT CHARTS



BEVEL 130A MILD STEEL

O₂ PLASMA AIR SHIELD

Plasma gas inlet: 120psi/8.4bar Shield gas inlet: 120psi/8.4bar















Shield Cap 97-0200

Shield 97-0255

Nozzle Retaining Cap 97-1365

Nozzle 97-0252

<u>Swirl Ring</u> 90-0179

<u>Electrode</u> 97-0249

Water Tube 90-0700

Note: Bevel angle range is 0° to 45°

4	Thickness	Pref	low	Cut	flow	Minimum Clearance	Torch-to-Work	Cutting Speed	Initial I	Pierce Height	Pierce Delay
=	Inches	O ₂ Plasma	Air Shield	O ₂ Plasma	Air Shield	Inches	Inches	Inches/Minute	In	Factor	Sec
2	0.135						0.10 - 0.34	240	0.20		0.1
<u> </u>	3/16				21		0.11 0.24	190	0.22		0.2
7	1/4						0.11 - 0.34	150	0.22		
ה	5/16						0.10 0.04	132	0.04	200	0.3
	3/8		23				0.12 - 0.34	110	0.24	200	
	1/2	15		84		0.08	0.13 - 0.34	80	0.26		0.5
i [5/8				15		0.15 - 0.34	60			0.7
	3/4				13		0.13 - 0.34	45	0.30		1.0
	1						0.16 - 0.34	20		190	1.8
	1-1/4∆		33				0.18 - 0.34	15	0.40	220	4.0
	1-1/2		აა				0.10 - 0.34	10		Edge start	

- Δ Suggestions for piercing 1-1/4 in (32mm) mild steel:
 - 1. Turn preflow on during IHS
 - 2. Use ohmic contact during IHS
 - 3. Use pierce complete when piercing

† American Torch Tip Company is in no way affiliated with the above-named manufacturer(s). References to the above-named machines, torches and numbers are for your convenience only. American Torch Tip is not necessarily authorized by the above-named manufacturer(s) to provide replacement parts. Most parts advertised for sale are made by, or for, American Torch Tip Company and other parts, as indicated, are original parts manufactured by the above-named OEM and are simply being resold by American Torch Tip Company. Part numbers followed by an * are manufactured by the respective OEM.

90-7910



CUT CHARTS



METRIC

Thickness	Pref	flow	Cut	flow	Minimum Clearance	Torch-to-Work	Cutting Speed	Initial	Pierce Height	Pierce Delay	
mm	O ₂ Plasma	Air Shield	O ₂ Plasma	Air Shield	mm	mm	mm/Minute	mm	Factor	Sec	
3						2.5 - 8.6	6505	5.0		0.1	
4				01		2.8 - 8.6	5550	5.6		0.2	
5				21			4795				
6							4035				
8		23				3.0 - 8.6	3360		200	0.3	
10	15	20	84		2.0	3.0 - 6.6	2680	0.0			
12					2.0	3.3 - 8.6	2200	6.6	6.6	0.5	
15				ı	15		3.8 - 8.6	1665		1	0.7
20				15		3.0 - 0.0	1050	7.6		1.0	
25							4.0 - 8.6	550		190	1.8
32∆		33				4.5 - 8.6	375	10.2	220	4.0	
38		33				4.0 - 0.0	255		Edge start		

Select Gases Set Preflow Set Cutflow	Arc Voltage	Speed	Marking	o-Work	Torch-	Amperage	.Hi a	C-+ C	oflow	Cot D	Casas	Calaat
Amps mm Inches mm/Minute Inches/Mi	nutes Volts	Inches/Minutes	mm/Minute	Inches	mm	Amps	utilow	Set C	ellow	Set Pi	Gases	Select
N ₂ N ₂ 10 10 10 10 15 2.5 0.10 6350 250	130	250	6350	0.10	2.5	15	10	10	10	10	N ₂	N ₂
Air Air 50 10 50 10 15 3.0 0.12 2540 100	75							=0	4.0			۸:۰

△ Suggestions for piercing 32mm (1-1/4 in) mild steel:

- 1. Turn preflow on during IHS
- 2. Use ohmic contact during IHS
- 3. Use pierce complete when piercing

† American Torch Tip Company is in no way affiliated with the above-named manufacturer(s). References to the above-named machines, torches and numbers are for your convenience only. American Torch Tip is not necessarily authorized by the above-named manufacturer(s) to provide replacement parts. Most parts advertised for sale are made by, or for, American Torch Tip Company and other parts, as indicated, are original parts manufactured by the above-named OEM and are simply being resold by American Torch Tip Company. Part numbers followed by an * are manufactured by the respective OEM.

90-7910