

CUT CHARTS



138 STYLES

Light preheat tip designed for fine contour cutting wth hand cutting torches and is recommended for machine cutting applications. Six (6) preheat flames.

| Material Thickness | Tip Size | Drill Size | Oxygen PSI | Oxygen CFH | Fuel PSI | Fuel CFH | Cutting Speed Range (IPM) |
|-----------------------|----------|------------|------------|------------|----------|----------|---------------------------|
| 1/8" | 00 | 69 (.029) | 30 | 30 | 1 1/2 | 11 | 21-24 |
| 1/4" | 0 | 64 (.036) | 30 | 54 | 3 | 11 | 18-22 |
| 3/8" | 1 | 57 (.043) | 30 | 76 | 3 | 13 | 18-21 |
| 3/4" | 2 | 55 (.052) | 40 | 127 | 3 | 15 | 14-16 |
| 1 1/2" | 3 | 53 (.059) | 45 | 183 | 3 | 16 | 11-14 |
| 2 1/2" | 4 | 50 (.070) | 50 | 257 | 3 | 20 | 8-10 |

